

5647 FRUTAS AVE.



**BUILDING AND STANDARDS BOARD AGENDA ITEM #4 FOR  
WEDNESDAY, JULY 30, 2014**

**ENVIRONMENTAL SERVICES DEPARTMENT  
CODE COMPLIANCE DIVISION**

**MEMORANDUM  
July 17, 2014**

**TO:** The Honorable Chairman and Board Members

**THROUGH:** Victor Morrison-Vega, Deputy Director, City Development Department

**FROM:** Ron Roth, C.B.O., Deputy Building Official

**SUBJECT:** 5647 Frutas Ave., El Paso, TX 79905

The following is a brief chronology of the investigation of the referenced location:

- 1) First investigated on January 24, 2008. Recently inspected on May 21, June 26, July 10 and July 16, 2014. The structures were condemned on July 30, 2008 to be secured and cleaned of all weeds, trash and debris, and maintained secure and clean thereafter. The property caught fire on or about May 01, 2014. This single family dwelling was built on or about 1963. The main structure has an illegal addition and there is a dilapidated accessory structure. The structures are open to unwanted entry and structurally unsound due to lack of maintenance, exposure to the elements and fire damage. Attempts to maintain the structures secure have been unsuccessful.
- 2) A certified condemnation letter was mailed to the owner Emilio Sandoval.
- 3) Certified notices of the public hearing scheduled for July 30, 2014 were mailed to the owner and all interested parties on July 10, 2014.
- 4) As of July 14, 2014, \$1,690.98 is owed in taxes.

The owner has been notified of the property violations at this property. To date there has been no response or corrective action taken, and therefore the Department recommends that it be found:

- 1) That the structures remain condemned as substandard, and unfit for habitation or use and a hazard to the public health, safety, and welfare; and
- 2) That the structures are not in substantial compliance with the municipal ordinances regulating fire protection, structural integrity, and disposal of refuse; and
- 3) That the structures' certificate of occupancy remain revoked; and
- 4) That the structures cannot be rehabilitated; and
- 5) That the structures be demolished within thirty (30) days; and
- 6) That the premises be cleaned and maintained clean of all trash, and debris within 30 days; and
- 7) That upon failure by the owner or any other interested party to comply with the order of the Building and Standards Commission the City may take whatever action is necessary to bring the property into compliance, and place a lien on the property for the work which will be done by the City.

Code Compliance Division  
May 28, 2014  
**NOTICE OF VIOLATION**

Emilio Sandoval  
5647 Frutas Ave  
El Paso, TX 79905-1726

Re: 5647 Frutas Ave  
Blk: 5 Hughes S/D Blk 1 Alameda Acres  
Lot: 27  
Zoned: R-5  
ENHS14-00935  
9171999991703077006950

To All Owners, Lienholders, and Mortgagees:

An inspection at the above referenced address has revealed that the structure is in violation of the El Paso Municipal Code, Chapter 18.50, Property Maintenance Code, which states:

**18.50.108.1 General.**

When a structure or equipment is found by the Director to be unsafe, or when a structure is found unfit for human occupancy, or is found unlawful, such structure or equipment shall be condemned pursuant to the provisions of Title 2.38 of the Municipal Code.

The El Paso Municipal Code Chapter 18.50 International Property Maintenance Code defines unsafe structure as follows:

**18.50.108.1.1 Unsafe Structures.**

An unsafe structure is one that is found to be dangerous to the life, health, property or safety of the public or the occupants of the structure by not providing minimum safeguards to protect or warn occupants in the event of fire, or because such structure contains unsafe equipment or is so damaged, decayed, dilapidated, structurally unsafe or of such faulty construction or unstable foundation, that partial or complete collapse is possible

**18.50.108.1.2 Unsafe Equipment.**

Unsafe equipment includes any boiler, heating equipment, elevator, moving stairway, electrical wiring or device, flammable liquid containers, or other equipment on the premises or within the structure that is in such disrepair or condition that such equipment is a hazard to life, health, property or safety of the public or occupants of the premises or structure.

**18.50.108.1.3 Structure Unfit for Human Occupancy.**

A structure is unfit for human occupancy whenever the Director finds that such structure is unsafe, unlawful or, because of the degree to which the structure is in disrepair or lacks maintenance, is unsanitary, vermin or rat infested, contains filth or contamination, or lacks ventilation, illumination, sanitary or heating facilities or other essential equipment required by this code, or because the location of the structure constitutes a hazard to the occupants of the structure or to the public

The structure located at **5647 Frutas Ave, El Paso, TX 79905** is in violation of the requirements found in the following sections of the 2009 International Property Maintenance Code as adopted in the El Paso City Code, Chapter 18.50, Property Maintenance Code:

- a. All exterior property, accessory structures and premises shall be maintained in a clean, safe and sanitary condition. All accessory structures, including detached garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9 ]
- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All exterior property and premises, and the interior of every structure, shall be free from any accumulation of rubbish or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent infestation. All structures in which insects or rodents are found shall be promptly exterminated by approved processes that will not be injurious to human health. After pest elimination, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3 ]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5 ]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]

- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]
- o. The drainage of roofs and paved areas, yards and courts, and other open areas on the premises shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1,604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and approved manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the public way. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4 ]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

As a result of the aforementioned violations, the following action may be taken:

- a. This case is being submitted to the City Building and Standards Commission for unsafe structures proceedings. The Building and Standards Commission will decide if the structure is unsafe and if it should be vacated and secured, or demolished as per Title 2.38 of the El Paso Municipal Code.

- b. By authority of Chapter 18.02.103.10.3.3 of the El Paso Municipal Code the electrical service at this property may be disconnected at the request of the Environmental Services Department, Code Compliance Division because of Electrical Code violations.

Many of these corrections will require a permit. Permits for commercial or rental property must be taken out by a bonded and insured contractor who is registered with the City of El Paso.

According to the real property records of El Paso County, you own the real property described in this notice. If you no longer own the property, you must execute an affidavit stating that you no longer own the property and stating the name and last known address of the person who acquired the property from you. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division office, 7969 San Paulo Dr., El Paso, Texas, 79907, no later than the 20th day after the date you receive this notice. If you do not send the affidavit, it will be presumed that you own the property described in this notice, even if you do not.

Should you have any questions regarding this matter, please contact me at 599-6290.

Janeth Loya  
Building Inspector

## **NOTICE OF PUBLIC HEARING**

### **To all interested parties:**

The owners, mortgagee, lien holders and any others with a legal interest in the property described below are hereby ordered to appear before the Building and Standards Commission, herein after referred to as the “Commission”, at the following time and place:

**LOCATION:** City Hall, City Council Chambers, 300 N. Campbell Street, 1<sup>st</sup> Floor, El Paso, Texas 79901

**DATE:** July 30, 2014

**TIME:** 5:30 p.m.

**PROPERTY:** 5647 Frutas Avenue, Lot 27, Block 5, MAP OF HUGHES SUBDIVISION OUT OF BLOCK 1, ALAMEDA ACRES, an addition to the City of El Paso, El Paso County, Texas, according to the Plat thereof recorded in Volume 13, Page 16, Plat Records of El Paso County, Texas.

The property has been determined to be substandard based upon violations of the minimum standards of the 2009 Building Codes, adopted and incorporated in the El Paso City Code, Chapter 18, more specifically addressed below.

According to the real property records of El Paso County, and other relevant public records, Emilio Sandoval, 5647 Frutas Avenue, El Paso, Texas 79905-1726, is the owner, herein after referred to as the “Owner” of the Property. If you no longer own or have an interest in the Property, you must execute an affidavit stating that you no longer own or have an interest in the Property and stating the name and last known address of the person who acquired the property from you, if applicable. The affidavit must be delivered in person or by certified mail, return receipt requested, to the Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907, no later than the 20<sup>th</sup> day after the date you receive this notice. If you do not execute and deliver the affidavit, it will be presumed that you own or have an interest in the Property, even if you do not.

On or about May 21, 2014, an inspection of the property was conducted by the Building Safety Division (formerly Environmental Services Code Compliance Division) and the following violations were identified:

- a. All *exterior property, accessory structures* and *premises* shall be maintained in a clean, safe and sanitary condition, All accessory structures, including *detached* garages, fences and walls, shall be maintained structurally sound and in good repair. [Sec. 302.1, 302.2, 302.3, 302.4, 302.5, 302.6, 302.7, 302.8, 302.9 ]

- b. The exterior of a structure shall be maintained in good repair, structurally sound and sanitary so as not to pose a threat to the public health, safety or welfare. [Sec. 304.1, 304.1.1 conditions 1,2,3,4,5,6,7,8,9,10,11,12,13, 304.2, 304.3, 304.4, 304.5, 304.6, 304.7, 304.8, 304.9, 304.10, 304.11, 304.12, 304.13, 304.14, 304.15, 304.16, 304.17, 304.18]
- c. The interior of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 305.1, 305.2, 305.3, 305.4, 305.5, 305.6]
- d. The components of a structure and equipment therein shall be maintained in good repair, structurally sound and in a sanitary condition. [Sec. 306.1, 306.1.1 conditions 1,2,3,4,5,6,]
- e. All *exterior property* and *premises*, and the interior of every structure, shall be free from any accumulation of *rubbish* or garbage. [Sec. 308.1, 308.2, 308.2.1, 308.2.2, 308.3, 308.3.1, 308.3.2]
- f. All structures shall be kept free from insect and rodent *infestation*. All structures in which insects or rodents are found shall be promptly exterminated by *approved* processes that will not be injurious to human health. After *pest elimination*, proper precautions shall be taken to prevent reinfestation. [Sec.309.1, 309.2, 309.3, 309.4, 309.5]
- g. The building must comply with the minimum criteria and conditions for light. [Sec.402.1, 402.2, 402.3 ]
- h. The building must comply with the minimum criteria and conditions for ventilation. [Sec.403.1, 403.2, 403.3, 403.4, 403.5 ]
- i. The requirement for Privacy, minimum room dimensions, prohibited occupancy or food preparation spaces not met. [Sec.404.1, 404.2, 404.3, 404.4, 404.5, 404.6, 404.7]
- j. The building must comply with the minimum criteria of the provisions for required facilities. [Sec. 502.1, 502.2, 502.3, 502.4,502.4.1, 502.5]
- k. The building must comply with the minimum criteria of the provisions for toilet rooms. [Sec. 503.1, 503.2, 503.3, 503.4]
- l. The building must comply with the minimum criteria of the provisions for plumbing systems and fixtures. [Sec. 504.1, 504.2, 504.3]
- m. The building must comply with the minimum criteria of the provisions for water systems. [Sec. 505.1, 505.2, 505.3, 505.4]
- n. The building must comply with the minimum criteria of the provisions for sanitary drainage systems. [Sec.506.1, 506.2, 506.3]



- o. The drainage of roofs and paved areas, *yards* and courts, and other open areas on the *premises* shall not be discharged in a manner that creates a public nuisance. [Sec. 507.1]
- p. The building must comply with the minimum criteria of the provisions for heating facilities. [Sec. 602.2, 602.3, 602.4, 602.5]
- q. All mechanical equipment and fireplaces shall be properly installed and maintained. [Sec.603.1, 603.2, 603.3, 603.4, 603.5, 603.6]
- r. The building must comply with the minimum criteria of the provisions for electrical facilities. [Sec. 604.1,604.2, 604.3, 604.3.1, 604.3.1.1, 604.3.2, 604.3.2.1]
- s. All electrical equipment, wiring and appliances shall be properly installed and maintained in a safe and *approved* manner. [Sec. 605.1, 605.2, 605.3]
- t. Duct systems shall be maintained free of obstructions and shall be capable of performing the required function. [Sec. 607.1]
- u. Means of egress & Emergency escape opening - A safe, continuous and unobstructed path of travel has not been provided from all points in the building or structure to the *public way*. [Sec. 702.1, 702.2, 702.3, 702.4]
- v. The required fire-resistance rating of fire-resistance-rated walls, fire stops, shaft enclosures, partitions and floors shall be maintained. [Sec. 703.1, 703.2]
- w. All systems, devices and equipment to detect a fire, actuate an alarm, or suppress or control a fire or any combination thereof shall be maintained in an operable condition at all times. [Sec. 704.1, 704.1.1, 704.2, 704.3, 704.4 ]
- x. The structure needs to be secured from unwanted entry and ongoing vandalism, and the premises need to be cleaned of all trash and debris within (30) days from receipt of this letter. [Sec. 108.2]
- y. The repairs to the structural elements and/or service systems referred to in the previous sections must be completed within 30 days of your receipt of this letter. If, due to the scope and complexity of the work more time is needed, you must make this request to the Environmental Services Department, Code Compliance Division.

The Owner is entitled to show cause that the Property is safe, does not constitute dangerous structures and should not be declared a nuisance and ordered abated by presenting relevant evidence and testimony. If the Owner advocates for repair, then they bear the burden of proof to demonstrate the scope of any work that may be required to bring the property into compliance with Chapter 18.50 and the time it will take to reasonably perform the work. The allowable time periods for repair are governed by Texas Local Government Code, Sections 214.001(h), (i), (j) and (k). Any document relied upon to demonstrate that the Property is safe or that it can be repaired must be presented to the Commission at the hearing, including building plans, specifications, drawings, or reports from professionals and any other relevant documentation.

If the Owner fails to comply with the order of the Commission the City may pursue one or more of the following actions:

Perform any and all work necessary to bring the property into compliance with the Commission's order;

Assess civil penalties, provided for in the Commission's order, in an amount not to exceed \$1,000 per day or \$10 per day if the Property has a homestead exemption, that will accrue interest of 10% per year until paid in full;

Appoint a receiver as permitted by state law; and

Any other remedies permitted by state law.

Commission orders may be appealed to the State District Court within 30 days of the final order. The Commission's authority and procedures in regard to a Dangerous Structure Hearing may be found in Chapter 2.38 of the El Paso City Code and in their duly adopted bylaws. The bylaws may be obtained at the Code Compliance Division of Environmental Services, 7969 San Paulo Drive, El Paso, Texas 79907 or by calling (915) 599-6290.

This notice will be recorded in the real property records of El Paso County and will be binding on subsequent grantees, lien holders or other transferees of an interest in the Property.

The City Clerk is ordered to provide notice of this hearing to the record owners and all other interested parties, required by law, who are listed following this notice, and file this notice in the real property records of El Paso County.

**FAILURE OF THE OWNER AND/OR LIENHOLDER OR MORTGAGEE TO TAKE THE ORDERED ACTION MAY RESULT IN THE CITY TAKING THE ORDERED ACTION AND FILING A LIEN AGAINST THE PROPERTY.**

The City of El Paso appreciates your cooperation and prompt attention to remedying the nuisances on the Property. Please do not hesitate to contact me should you have any additional questions, comments or concerns relative to this notice.

APPROVED AS TO FORM

APPROVED AS TO CONTENT

---

Wendi N Vineyard  
Assistant City Attorney

---

Ron Roth, C.B.O.  
Deputy Building Official

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice of Public Hearing regarding the property located at **5647 Frutas Avenue** was filed with the County Clerk's Office, the official public records of real property for El Paso County.

---

Richarda Duffy Momsen

Executed this \_\_\_\_ day of \_\_\_\_\_, 2014 on behalf of the City of El Paso, Texas, by Richarda Duffy Momsen in her capacity as City Clerk.

STATE OF TEXAS  
COUNTY OF EL PASO

Subscribed and sworn to before me, this \_\_\_\_ day of \_\_\_\_\_, 2014.

---

Notary Public

I, RICHARDA DUFFY MOMSEN, City Clerk of the City of El Paso, hereby certify that a true and correct copy of the foregoing Notice regarding the property located at **5647 Frutas Avenue** was PUBLISHED in the official City newspaper on the \_\_\_\_ day of \_\_\_\_\_, 2014.

\_\_\_\_\_  
Richarda Duffy Momsen

I certify that a true and correct copy of the foregoing Notice regarding the property at **5647 Frutas Avenue** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Emilio Sandoval  
5647 Frutas Avenue  
El Paso, Texas 79905-1726

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

I certify that a true and correct copy of the foregoing Notice regarding the property at **5647 Frutas Avenue** was HAND-DELIVERED to:

City of El Paso  
C/O City Clerk  
300 N. Campbell  
El Paso, TX 79901

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

I certify that a true and correct copy of the foregoing Notice regarding the property at **5647 Frutas Avenue** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Governor of the Ysleta Del Sur Pueblo Indian Tribe  
AKA Tigua Indian Community  
119 S. Old Pueblo Road  
El Paso, Texas 79907

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

I certify that a true and correct copy of the foregoing Notice regarding the property at  
**5647 Frutas Avenue** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso Central Appraisal District  
5801 Trowbridge Ave.  
El Paso, Texas 79925

Date: \_\_\_\_\_

Time: \_\_\_\_\_

Inspector: \_\_\_\_\_

I certify that a true and correct copy of the foregoing Notice regarding the property at  
**5647 Frutas Avenue** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

El Paso County Clerk, Probate Dept.  
500 E. San Antonio Avenue, Suite 105  
El Paso, Texas 79901

Date: \_\_\_\_\_

Time: \_\_\_\_\_

Inspector: \_\_\_\_\_

I certify that a true and correct copy of the foregoing Notice regarding the property at  
**5647 Frutas Avenue** was MAILED CERTIFIED-RETURN RECEIPT REQUESTED to:

Delgado, Acosta, Spencer  
Linebarger, Heard & Perez, LLP  
Attn: Bonnie Cooper  
221 N. Kansas Suite 1400  
El Paso, TX 79901

Date: \_\_\_\_\_

Time: \_\_\_\_\_

Inspector: \_\_\_\_\_

I certify that a true and correct copy of the foregoing Notice was POSTED at  
**5647 Frutas Avenue, El Paso, Texas.**

Date: \_\_\_\_\_

Time: \_\_\_\_\_

Inspector: \_\_\_\_\_



# UNSAFE STRUCTURES REPORT

## BUILDING SAFETY DEPARTMENT

**DATE OF EXAMINATION:** July 16, 2014

**REP. DISTRICT:** 3

**ADDRESS:** 5647 Frutas Avenue

**ZONED:** R-5

**LEGAL DESCRIPTION:** Lot 27, Block 5, MAP OF HUGHES SUBDIVISION OUT OF BLOCK 1, ALAMEDA ACRES, an addition to the City of El Paso, El Paso County, Texas, according to the plat thereof recorded in Volume 13, Page 16, Plat Records of El Paso County, Texas.

**OWNER:** Emilio Sandoval

**ADDRESS:** 5647 Frutas Ave., El Paso, TX 79905-1726

**BUILDING USE:** Abandoned Single-Family Dwelling with Illegal Addition and Accessory Structure.

**TYPE OF CONSTRUCTION:** Type V, main structure constructed of adobe walls covered with plaster, wood framed roof system and concrete slab foundation. Wood framed w/corrugated sheet metal covering addition constructed without permits. Accessory structure constructed of metal.

**FOOTINGS:** Unable to determine due to subterranean placement.

**CONDITION:** A structural engineer should be hired to evaluate actual condition.

**FOUNDATION WALL:** N/A

**CONDITION:** N/A

**FLOOR STRUCTURE:** Concrete slab on grade and wood framed floor system.

**CONDITION:** Poor. Dilapidated and fire damaged floor system with visible signs of failure throughout the dwelling. A structural engineer should be hired to evaluate actual condition.

**EXTERIOR WALLS:** Wood framed Adobe walls with stucco exterior finish, some corrugated steel in an illegal addition.

**HEIGHT:** 10 ft. +/-

**THICKNESS:** 16 in. +

**CONDITION:** Poor. Plaster and metal or wood covering has fallen in several areas exposing the underlying adobe to the elements causing structural deficiencies and compromising the integrity of the structure. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

**INTERIOR WALLS & CEILINGS:** Combination of adobe with plaster and wood framed walls w/gypsum board; combination of suspended ceiling, some wood lath w/plaster coating and gypsum board ceilings. Illegal addition constructed of drywall covered wall and ceilings.

**CONDITION:** Poor. Most of the ceiling has collapsed due lack of maintenance, fire occurrence and water infiltration allowing the elements and the exterior light to seep through. A structural engineer should be hired to evaluate the structural elements of the building and submit a report on the corrections required to make the building safe.

**ROOF STRUCTURE:** Flat roof with roll roofing composition material with 1" x 8" sub-decking and 2" x 4" rafters.

**CONDITION:** Poor. Noticeable leaks throughout the dwelling; the system has been heavily damaged by fire occurrence. A registered roofing contractor will need to be hired to evaluate the entire roofing system and submit a report of his findings to this department on the corrective action required to bring the system up to minimum code compliance.

**DOORS, WINDOWS, ETC.:** No windows or doors in place.

**CONDITION:** Non-existent

**MEANS OF EGRESS:** Non-compliant.

**CONDITION:** Poor.

**PLUMBING:** Substandard plumbing. A licensed plumber should be hired to bring the plumbing system up to code.

**ELECTRICAL:** Substandard electrical. A licensed electrician should be hired to bring the electrical system up to code.

**MECHANICAL:** Substandard mechanical. A licensed mechanical contractor should be hired to bring the mechanical system up to code.

**IF CONDEMNED, HOW MANY PERSONS WILL BE AFFECTED:** 0

**WARNING POSTED:** YES

**BARRICADED:** NO

**POLICE AID REQD.:** NO

**REMARKS:** This single family dwelling was built on or about 1963. The main structure has an illegal addition. There is an accessory structure. The structures were found open, abandoned and in a serious case of disrepair. The structures were condemned on July 30, 2008 to be secured and cleaned within thirty (30) days and maintained clean and secure thereafter. The structures are showing signs of structural deficiencies due to lack of maintenance and exposure to the elements and have suffered heavy structural damage during a fire which occurred on or about May 01, 2014. The structures should be demolished within thirty (30) days. The premises should be cleaned of all weeds, trash and debris within thirty (30) days and be maintained clean of all weeds, trash and debris.

Janeth Loya

**Building Inspector**

# TAX REPORT

Appraisal & Collection Technologies - EL PASO

Action Edit Query Record Field Help Entitlements Accounts Statements Window

ORACLE

Account Status

Prev. Acc... Next Acc... Prev. Owner Next Owner Acct History Acct Summary **Notes** Documents Go To:

EVAR  
ACT8006 v1.245 07/14/2014 10:47: ACTEP

STATUS DETAIL Expand Fees Summary

**Account Information**

Account No.  Roll Code

Certified Owner

Parcel Address

Amount Due as of  CAD No.

**Tax Units**

Tax Unit Description

List of Tax Units

**Tax Unit, Yr, Rec. Type**

Tax Unit

Year

Rec. Type

**Amount Due/Paid Information**

Year	Gross Value	H	O	V	D	Base Levy	Paid Levy	Write-Off	Remaining Levy	Fees	Refund	Amount Due
2013	\$5,699					\$153.03	\$0.00	\$0.00	\$153.03	\$27.55	\$0.00	\$180.58
2012	\$5,699					\$148.66	\$0.00	\$0.00	\$148.66	\$82.55	\$0.00	\$231.21
2011	\$5,699					\$146.02	\$0.00	\$0.00	\$146.02	\$102.01	\$0.00	\$248.03
2010	\$5,699					\$144.84	\$0.00	\$0.00	\$144.84	\$122.03	\$0.00	\$266.87
2009	\$5,699					\$141.97	\$0.00	\$0.00	\$141.97	\$140.00	\$0.00	\$281.97
2008	\$9,064					\$226.49	\$0.00	\$0.00	\$226.49	\$255.83	\$0.00	\$482.32
2007	\$9,064					\$228.34	\$228.34	\$0.00	\$0.00	\$15.99	\$0.00	\$0.00
2006	\$8,753					\$253.33	\$253.33	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2005	\$8,753					\$273.31	\$273.31	\$0.00	\$0.00	\$24.60	\$0.00	\$0.00
<b>Totals</b>						<b>\$3,781.57</b>	<b>\$2,820.56</b>	<b>\$0.00</b>	<b>\$961.01</b>	<b>\$789.60</b>	<b>\$0.00</b>	<b>\$1,690.98</b>

Last Payment Date

Last Payer

9:47 AM  
7/14/2014